

Step1: Open "1.USB Driver"-->run the "1.setup.exe";

Step2: Open "2. Software Driver"-->upzid"NILWCVIRTE2009P1.zip"-->run the "NILWCVIRTE2009SP1.exe"

Step3: Open "3. AOTF"-->Open"AOTF-RF2"-->run the"AOTFcontroller.exe"

If we run the "1.USB Driver failure" for win 10 PC system, please try the following method.
Start-> Update and satfy-> recover->advanced options->troubleshooting->advanced options->boot setting->Disable driver signing

针对 win10 系统，若驱动安装失败解决办法如下：

开始选项 -> 设置 -> 更新和安全 -> 恢复->高级选项中的 立即重启->疑难解答->高级选项->启动设置->重启->禁用驱动程序强制签名，然后重新安装软件驱动。